

Rubicon Trail Site Assessment

March 21, 2014

Crew: Vickie Sanders, Byron Saylor

Weather Conditions: The weather conditions for the Rubicon Trail were clear and warm. The temperature on the trail was approximately 36(F) at 7:30 am and 48(F) around 12:30 p.m. The summary of weather conditions up to this day are as followed:

2014		17-Mar	18-Mar	19-Mar	20-Mar	21-Mar
GT	Precip (in)	0.00	0.00	0.00	0.00	0.00
	Avg Temp (F)	51	52	56	58	57
SLT	Precip (in)	0	0	0	0	0
	Avg Temp (F)	43	36	40	44	42
R2	Snow Depth (in)	25	25	24	23	23
	Avg Temp (F)	45	38	31	38	41
LL	Precip (in)	0	0	0	0	0
	Low Temp(F)	34	31	32	34	33
	High Temp(F)	49	46	52	53	51
	Ave Temp(F)	41	38	41	44	42

Reference Loon Lake Elevation: ~6,500 ft

GT = Georgetown; elevation: 2,880 ft <http://classic.wunderground.com/cgi-bin/findweather/getForecast?query=95634>

SLT= South Lake Tahoe; elevation: 6,623 ft <http://classic.wunderground.com/cgi-bin/findweather/getForecast?query=38.89361191,-119.99527740&MR=1>

R2 – Rubicon#2 Snotel Site; elevation: 7,689 ft <http://www.wcc.nrcs.usda.gov/nwcc/site?sitenum=724&state=ca>

LON –Loon Lake; elevation: 6,410 ft http://cdec.water.ca.gov/cgi-progs/stationInfo?station_id=LON

Trail Sections (Areas in grey not observed):

Wentworth Springs Campground / Post Pile Grade /

Ellis Creek Tie Intersection / Walker Hill / Soup Bowl / Winter Camp / Little Sluice Area

Trail Conditions / Observations: We entered the Rubicon Trail from the Loon Lake entrance. We traveled from Loon Lake to Ellis Creek Intertie and then to Little Sluice. From Little Sluice we traveled back to Loon Lake via Gate Keeper. There were no vehicles seen on the Trail over the course of the day. We observed some vehicle tracks at some of the sites. Most of the BMP's were not covered with snow along the Trail. The ones that were exposed were functioning as designed. We did not monitor Wentworth Springs Campground and Post Pile due to mechanical issues.

County Assessment: As of this site visit for the conditions observed, the County has determined that the goals of the Saturated Soil Water Quality Protection Plan (SSWQPP) are being met. Observed water levels were low enough to not pose a risk of washing contaminants from the under carriage of vehicles pursuant to the monitoring protocols. The County will continue to monitor Trails conditions as weather conditions change.


Report reviewed by U.S. Forest Service on 28 March, 2014.

Reviewers: Richard Thornburgh, District Ranger, and Eric Nicita, Soils Scientist

**Rubicon Trail
El Dorado County Site Assessment
March 21, 2014**

Rubicon Trail Site Assessment March 21, 2014

Photo Monitoring:




Ellis Creek Intertie
RT Station 99+86.95

Water Depths: 0, 0, 0
(Average: 0)

Notes: The Rock Lined Channel (RLC) was exposed along with the Rock Energy Dissipator (RED). There was no snow run off at this time.

Rubicon Trail Site Assessment

March 21, 2014



Walker Hill
RT Station 170+80

Water Depths: .05, .05, .05
(Average: .05)

Notes: The Rock Slope Protection (RSP) was not fully exposed on both sides of the Trail. There was minimal snow melt run-off flowing down the hardened surface of the Trail, which discharges into a Rock Energy Dissipator.



Soup Bowl
RT Station 198+40.84

Water Depth: .1, .2, .2
(Average: .17)

Notes: The Rock Ditch Crossing (RDX) was exposed through the snow with snow melt run-off flowing through it.

Rubicon Trail Site Assessment March 21, 2014



Winter Camp
RT Station 209+58.39

Water Depth: .4, .6, .8
(Average: .6)

The Rock Fill (RF) was fully exposed and the run off was flowing over the RF. There was one out of the three measurements that was greater than 8" however the length did not exceed 10'. Per Condition 2 of the Protocol closure of the trail is not warranted at this time.



Little Sluice
RT 213+50.32

Water Depth: .05, .05, .05
(Average: .05)

The Rock Fill (RF) was mostly exposed through the snow. Where visible, the run off was flowing over the RF.